43

18

Today's Date	11/30/2022		Bus Name		AJ Knightrider				
Yr/Make/Model	1999 Prevost H3-45VIP		VIN#		2 P CV	V33495X1012599			
Mileage	645,908	/ ECM 7	768,798	Door Code	sys	t inop	Те	ch & Time:	MB -2.5
Engine Type	Detroit	Series 60	т	ransmission Type	Allison B	500	Genera	ator Gen I	Hours
Engine Serial #	06R04	425688		nsmission Serial#	6610092	179		2	59
	All and the second	A State of the sta	DOT	Compliance Items		1 Strate			
	OK	Repair	Technician's Note			Qty:	Per Piece:	Price:	Labor:
Driving Fog Lights		X	both inoperable	9		2			TBD
Gauge Lights		X	needs 3			3	\$3.80	\$11.40	1
Dash Lights						_	-		
ABS Light Headlights		X	light on						TBD
Brake Lights							-		
Clearance Lights		x	one upper red			1	\$41.58	\$41.58	1
Tail Lights			one upper red				φ41.00	φ41.50	
Turn Lights									
Escape Hatch Operational		x							
Windshield		X	none			+			TBD
Driver Glass	* X		driver side - ne	ed replaced		1	\$448.91	\$448.91	2
Windshield Wipers									
		N/A	·						
Upper Control Arms			straight axle						
Lower Control Arms	* N/A	N/A	straight axle						
Suspension - Front		X		er radius rod broken		4	\$20.02	\$80.08	6
Suspension - Rear		X	tag axle upper	radius rod		2	\$20.02	\$40.04	4
Power Steering	* X			-1			-		
Exhaust System/Muffler	* X			Drakes					
Front %	* 80%			Brakes			-		
Drive %	* 80%								
Tag%	* 80%		·						
Jake Brake	_								
Shock - Front									
Shock - Rear	* X								
				Tires					
Front %			18/32 18/32	- DOT 2022					
Drive %			18/32 18/32	18/32 18/32 - DOT	2022				
Tag %			18/32 18/32	- DOT 2022					
Wheelseals - Front									
Wheelseals - Rear	* X								
				Seat Belts					
Driver									
Jump		X	none			1	\$75.44	\$75.44	1
Passenger (if applicable)	* N/A	N/A						110	
				Other		102 212	HEARDIN AND A		
d/s outside drive wheel		X	rim cracked 1	Rx24.5		1	\$693.00	\$693.00	1.5
steer axle tie rods		X	needs both			2	\$989.79	\$1,979.58	2.5
			<u>.</u>						
				1				* 207.2	

1

-

5

			Conversion / Pue Interior		Bus Nan	ne: AJ Knig	htrider
	ОК	Repair	Conversion / Bus Interior Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Smoke/Co2 Detector		X	none	1	\$75.46	\$75.46	0.25
Switch Lights	X						
Switch Identification	X						
Water Pump Operation	X						
Fresh Water Drain	X						
Sewer Drain	X						
Air Vents Dash	X						
Air Vents Coach	X						
Driver Stereo	X						
BackUp Camera	N/A	N/A					
Driver Seat Operation	X			-			
Driver Seat	X						
Driver Seat							
			Finishes		Т		
Tile Condition	X						
Laminate Condition	X						
Shower Operational	N/A	N/A					
Air Pocket Doors	N/A	N/A					
Pocket Doors	N/A	N/A					
Cabinet Hardware	N/A	N/A					
Ceiling Mirrors	N/A	N/A					
Shower Head	N/A	N/A					
Sink Head	X						
Upholstery-Front	X						
Upholstery-Rear	X						
Window Tint	X						
Windshield Rubber	X						
			Fuel System				B. Come
Fuel Level	X		1/2 took				
Level Low System	X		1/2 tank				
	P. Marker	88	Bumpers				
Front Bumper	X						
Rear Bumper		X	needs replaced - see pg 6	1	\$3,542.00	\$3,542.00	incl
			Keys				
Door Code/Keypad		X	all inoperable				TBD
Door	X						IBU
Ignition	X	i				<u> </u>	
Engine		i	·				
Bays	X						
Cabinets/Interior	N/A	N/A	1				
			J				
	and the second		Other				
Rear Lounge Door		X	door knob missing	1	\$49.28	\$49.28	0.5
Trailer Hitch		X			WIG.20	φ /0.20	
			broken at all mounting points		+		TBD
			J 				

÷.

ų

	the manual		Electronics / Remotes		Bus Nan	ne: AJ Kniç	htrider
	014	Bassia		<u>.</u>			
Stereo Operational-F		Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Stereo Operational-R	X						
TV - Front	X		-				
TV - Rear							
Generator Remote Start		X	gen#2 needs starter	1	\$352.66	\$352.66	1.25
Genset Batteries	X						
Inverter Remote	N/A	N/A					
In-Motion Satellite Locks			unknown				
Speakers Operational	X						
Satellite Syst. Operational			unknown				
			Switches / Gauges / Lights				
Ship to Shore Switch/Plug	X						
Interior Lights 12v		X	hallway ceiling inoperable	all			TBD
Interior Lights 120v	X						
Light Switches	X						
Step Lights		X	inoperable	all			TBD
Buddy Light	X						
Driver Light	X						
Day/Night Shades		X	front lounge needs repair				TBD
Toilet	X						
Speedometer	X						
Fuel Gauge	X						
Temp Gauge	X						
Amp Gauge	N/A	N/A					
Volt Gauge	X						
DC Volt Gauge	N/A	N/A					
			Operations				
Roof Vent Fans	N/A	N/A		1	T	1	
Roof/CruiseAir Operational	X						
Roof/Cruise Air Filters	X						
Hot Water Heater	N/A	N/A					
Step Slide Operational	N/A	N/A					
Webasto	N/A	N/A					
Toe Kick Heaters	N/A	N/A					
Heat Pumps	X						
Fan Clutch	X						
City/Air Horn		X	inoporable				TPD
A/C Air Tank	N/A	N/A	inoperable				TBD
Alignment	X						
7 digiment			Duraka		1		
			Bunks				
Bunk Lights	X						
Condo Curtains		X	none				TBD
Bunk Curtains	X						
Mattresses	X						
Bunk TV's	N/A	N/A					
	L						

-

54

Bus Name: AJ Knightrider Engine & Mechanical							
	ОК	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
ECM Codes	X						
House Alternator Charge	N/A	N/A					
Drive AC Operational	X		1				
Coach AC Operational	N/A	N/A					
Coach AC Components	N/A	N/A					
HVAC Motor Brushes	N/A	N/A					
House Batteries	X						
Chassis Batteries	X						
Radiator Condition	X						
Belt Condition		X	needs crank to mitre box	3	\$26.18	\$78.54	0.25
Charge Air Cooler	X						
Airbags	X						
Transmission Seal	X						
Rear Main Seal	X						
Pinion Seal	X						
Mitre Box Seals	X						
50DN Seals	N/A	N/A	bosch alternator	_			
Charging	X X						
Mitre Box Dipstick							
Oil Dipstick Trans Dipstick							
Differential Oil							
Coolant Level							
Transmission Fluid Level							
Motor Oil Level							
Power Steering Level	X						
J. J							
		A MARTINE	Exterior				
Body Damage		X	see page 6	1			
Bay Door Shocks	X						
Bay Door Actuators		X	all inoperable - no keyless functions				TBD
Bay Door Operation	X			-			
Roof Inspection	X						
Roof Seals	X						
Mirror Chrome Condition	N/A	N/A					
Door Latches	X						
Trailer Wiring	X						
Rub Rails		X	see page 6				TBD
Side Glass	X						
Entrance Door Glass	X						
Shore Cord	X						
Awning Operable	N/A	N/A					
Docking Lights	X			1		1	
Mirror Operation	X			+	1	1	
Paint Repair		X					<u> </u>
		L			1	1	1

AJ Knightrider

ANNUAL VEHICLE INSPECTION REPORT

								E HISTORY RECORD
						REPO	ER	FLEET UNIT NUMBER
						-		
					DAT	E		
MOTOR CARRIER	OPERATOR				INSPECTOR'S NAME (PRINT	DR TYPE)		
ADDRESS					THIS INSPECTOR MEETS TH	QUALIFIC	ATION REC	QUIREMENTS IN SECTION 396.19.
CITY, STATE, ZIP	CODE				VEHICLE IDENTIFICATION (AND COM	PLETE)	
		ΠB	BUS		INSPECTION AGENCY/LOCAT	ION (OPTIC	DNAL)	
<u>[</u>	(OTHER)							
Provinsion of the second					ENTS INSPECTED			
OK REPAIR REPAIRED DATE	ITEM	OK	NEEDS REPAIR		ITEM	OK 题	DS REPAIRED	ITEM
	1. BRAKE SYSTEM		(1)		LOADING	stell all a		10. TIRES
×	a. Service Brakes				t(s) of vehicle or			a. Tires on any steering axle
+	b. Parking Brake System				dition of loading such	X		of a power unit.
×	c. Brake Drums or Rotors	X			t the spare tire or any	×		b. All other tires.
×	d. Brake Hose		-		t of the load or dunnag			11. WHEELS AND RIMS
×	e. Brake Tubing				fall onto the roadway.	Nº10		a. Lock or Side Ring
×	f. Low Pressure Warning	N	IA		tection against shifting	>	7	b. Wheels and Rims
	Device	-	-	car	The second	X		c. Fasteners
7	g. Tractor Protection Valve		1.		ntainer securement	MI		d. Welds
×	h. Air Compressor	a	14		vices on intermodal		T	12. WINDSHIELD GLAZING
HIL	i. Electric Brakes				lipment.			Requirements and exceptions
HID	j. Hydraulic Brakes				RING MECHANISM		1	as stated pertaining to any
NIA	k. Vacuum Systems	X			ering Wheel Free Play		-	crack, discoloration or vision
	2. COUPLING DEVICES	×			ering Column			reducing matter (reference
NIA	a. Fifth Wheels				nt Axle Beam and All		1	393.60 for exceptions).
N/A	b. Pintle Hooks	X			ering Components		-	13. WINDSHIELD WIPERS
×	c. Drawbar/Towbar Eye	1 1			er Than Steering			Any power unit that has an
	d. Drawbar/Towbar Tongue				lumn	X		inoperative wiper, or missing
	e. Safety Devices	×			ering Gear Box			or damaged parts that render
NA	f. Saddle-Mounts 3. EXHAUST SYSTEM	E			man Arm			it ineffective. 14. OTHER
	a. Exhaust system leaking	P	~		wer Steering		-	List any other condition(s)
	forward of or directly below	\vdash	×		l and Socket Joints			which may prevent safe
	the driver/sleeper	5	-	h. Tie i. Nu	Rods and Drag Links			operation of this vehicle.
	compartment.	1			ering System			
	b. Bus exhaust system	2	-	a. SUSP				tie Rod ends
X	leaking or discharging in				/ U-bolt(s), spring			Radius Rods bushing
	violation of standard.				iger(s), or other axle			crackedpim
	c. Exhaust system likely to		V		sitioning part(s) cracked			
	burn, char, or damage the		X		ken, loose or missing			windshield
X	electrical wiring, fuel supply,				ulting in shifting of an			11 Mar 1
	or any combustible part of		23		e from its normal positio	n.		
	the motor vehicle.	X			ing Assembly			
a manager at the Re-	4. FUEL SYSTEM		V		que, Radius or Trackin	g		
X	a. Visible leak.	1	X		mponents			
×	b. Fuel tank filler cap missing.		1	9. FRAM	and an			
x	c. Fuel tank securely attached.	X		a. Fra	me Members			
and the second second	5. LIGHTING DEVICES	X		_	e and Wheel Clearance			×
	All lighting devices and				ustable Axle			
	in lighting do nood and							
x	reflectors required by Part 393	P	14	Ass	semblies (Sliding			

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

© Copyright 2010 J. J. KELLER & ASSOCIATES, INC. Neenah, WI • USA • (800) 327-6868 jjkeller.com • Printed in the United States

.

ži,

ORIGINAL

400-FS-C2 3127 Rev. 6/10



6. 1

Bus Name:

AJ Knightrider



ENC©RE

BusForSale.com

Estimate

#26 11/30/2022

Bill To

4

-0

TOTAL

\$7,1	30.79

Expires: 12/30/2022

Expires	Exp. Close		Project	Sales Rep	
12/30/2022	11/30/20	122	AJ Knightrider		
Quantity	Item			Rate	Amount
1	Sub-Repair(s) DOT ESTIMATE				\$0.00
2	Sub-Repair(s) gauge lights			\$3.80	\$7.60
1	Sub-Repair(s) labor			\$150.00	\$150.00
1	Sub-Repair(s) clearance lights			\$41.58	\$41.58
1	Sub-Repair(s) labor			\$150.00	\$150.00
1	Sub-Repair(s) windshield			\$448.91	\$448.91
2	Sub-Repair(s) labor			\$150.00	\$300.00
4	Sub-Repair(s) driver side upper radius	rod		\$20.02	\$80.08
6	Sub-Repair(s) labor			\$150.00	\$900.00
2	Sub-Repair(s) tag axle upper radius roo	d		\$20.02	\$40.04
4	Sub-Repair(s) labor			\$150.00	\$600.00
1	Sub-Repair(s) jump seat belt			\$75.44	\$75.44
1	Sub-Repair(s) labor			\$150.00	\$150.00
1	Sub-Repair(s) driver side outside drive	wheel rim		\$693.00	\$693.00
1.5	Sub-Repair(s) labor			\$150.00	\$225.00
2	Sub-Repair(s) steer axle tie rods			\$989.79	\$1,979.58



ENCORE

BusForSale.com

ė,

Estimate

#26 11/30/2022

Quantity	Item	Rate	Amount
2.5	Sub-Repair(s) labor	\$150.00	\$375.00
	Subtotal		\$6,216.23
	Shop Supply / EPA Fee Shop Supply / EPA Fee	5%	\$310.81
1	Sub-Repair(s) TBD ITEMS: driving fog lights abs light on escape hatch		\$0.00
		Subtotal	\$6,527.04
		Tax Total (%)	\$603.75
		Total	\$7,130.79

Key Considerations -This quote is an estimate based on routing provided. A final invoice may be issued for any additional expenses. -Any additional expenses will be billed to the credit card on file (from the contract) for any additional expenses not included in the quote, but remain unpaid after 30 days from the invoice date. In addition, any tolls that are received by Encore after tour completion will be charged to the credit on file. (Most times the municipalities are tardy in sending out toll charges.) - Buses are not held until a signed contract and deposit are received.

Costs to Be Paid by Customer by Client Credit Card or "Float" while on Tour

-Parking -Tolls -Permits -Bus supplies and/or stock -Daily hotels on tour -Taxes

DOT Compliance

In accordance with the Federal DOT regulations the driver of the vehicle may not exceed 10 hours of driving time or 15 hours of on-duty time without taking an 8 hour off-duty break. The driver may not exceed 60 hours of on-duty time in a 7 day period or 70 hours of on-duty time in an 8 day period. With the new ELD laws in effect, there is an increased demand for double-drivers. If a double driver is needed, we must be notified within 14 days prior to the trip or we cannot be held responsible, or we may not be able to accommodate the request.



ENC©RE

BusForSale.com

Estimate

•

#27 11/30/2022

Bill To

4

TOTAL

\$5,0)88.	00
-------	------	----

Expires: 12/30/2022

Expires	Exp. Close	Project	Sales Rep	
12/30/2022	11/30/2022	AJ Knightrider		
Quantity	Item		Rate	Amount
1	Sub-Repair(s) smoke/co2 detector		\$75.46	\$75.46
0.25	Sub-Repair(s) labor		\$150.00	\$37.50
1	Sub-Repair(s) rear bumper (incl labor)		\$3,542.00	\$3,542.00
1	Sub-Repair(s) rear lounge door knob		\$49.28	\$49.28
0.5	Sub-Repair(s) labor		\$150.00	\$75.00
1	Sub-Repair(s) gen#2 starter		\$352.66	\$352.66
1.25	Sub-Repair(s) labor		\$150.00	\$187.50
3	Sub-Repair(s) belts		\$26.18	\$78.54
0.25	Sub-Repair(s) labor		\$150.00	\$37.50
	Subtotal			\$4,435.44
	Shop Supply / EPA Fee Shop Supply / EPA Fee		5%	\$221.77
	Subtotal TBD ITEMS: keypad trailer hitch interior lights step lights day/night shades city/air horn condo curtains bay door actuators rub rails			\$4,657.21



ENCORE

BusForSale.com

ė,

Estimate

#27 11/30/2022

Subtotal	\$4,657.21
Tax Total (%)	\$430.79
Total	\$5,088.00

Key Considerations -This quote is an estimate based on routing provided. A final invoice may be issued for any additional expenses. -Any additional expenses will be billed to the credit card on file (from the contract) for any additional expenses not included in the quote, but remain unpaid after 30 days from the invoice date. In addition, any tolls that are received by Encore after tour completion will be charged to the credit on file. (Most times the municipalities are tardy in sending out toll charges.) - Buses are not held until a signed contract and deposit are received.

Costs to Be Paid by Customer by Client Credit Card or "Float" while on Tour

-Parking -Tolls -Permits -Bus supplies and/or stock -Daily hotels on tour

-Taxes

DOT Compliance

In accordance with the Federal DOT regulations the driver of the vehicle may not exceed 10 hours of driving time or 15 hours of on-duty time without taking an 8 hour off-duty break. The driver may not exceed 60 hours of on-duty time in a 7 day period or 70 hours of on-duty time in an 8 day period. With the new ELD laws in effect, there is an increased demand for double-drivers. If a double driver is needed, we must be notified within 14 days prior to the trip or we cannot be held responsible, or we may not be able to accommodate the request.

