

Yr/Make/Model 12/19/24
VAN HOOB 2045
Mileage 295731
Engine Type DETROIT 60 SERIES
Engine Serial # 06R0767479

Transportation
VIN# YE22C16B952046544
Door Code N/A Tech & Time (10) 1.0
Transmission Type ALLISON 3500 Generator
Transmission Serial# 170615 Gen Hours N/A
DOT Compliance Item

Driving Fog Lights *	☒	☒	N/A				
Gauge Lights *	☐	☐					
Dash Lights *	☒	☐					
ABS Light *	☒	☐					
Headlights *	☒	☐					
Brake Lights *	☒	☐					
Clearance Lights *	☒	☐					
Tail Lights *	☒	☐					
Turn Lights *	☒	☐					
Escape Hatch Operational *	☒	☐					
Windshield *	☐	☐					
Driver Glass *	☒	☐					
Windshield Wipers *	☒	☐					
Upper Control Arms *	☒	☐					
Lower Control Arms *	☒	☐					
Suspension - Front *	☒	☐					
Suspension - Rear *	☒	☐					
Power Steering *	☒	☐					
Exhaust System/Muffler *	☒	☐					

Front % *	☒	☒	Pads & rotors				
Drive % *	☒	☒	rotor cracked on d.s.				
Tag % *	☒	☒	rotor pads				
Jake Brake *	☐	☐					
Shock - Front *	☒	☐					
Shock - Rear *	☐	☒	rotted out				

Front % *	☐	☒	needs tires				
Drive % *	☐	☒	needs tires				
Tag % *	☐	☒	needs tires				
Wheelseals - Front *	☒	☐					
Wheelseals - Rear *	☒	☐					

Driver *	☒	☐					
Jump *	☐	☐	N/A				
Passenger (if applicable) *	☐	☐	N/A				

LICENCE PLATE	☐	☒	LIGHT OUT				
DRIVER INFO	☐	☒	INSP - NO READINGS				
DISPLAY	☐	☐					
	☐	☐					

***Busforsale.com* ~ Bus Inspection**

Bus Name: 0

Conversion / Bus Interior

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Smoke/Co2 Detector							
Switch Lights							
Switch Identification							
Water Pump Operation							
Fresh Water Drain							
Sewer Drain							
Air Vents Dash							
Air Vents Coach							
Driver Stereo							
BackUp Camera	✓		7/4				
Driver Seat Operation	✓						
Driver Seat	✓						

Finishes

Tile Condition	☐	☐					
Laminate Condition	☐	☐					
Shower Operational	☐	☐					
Air Pocket Doors	☐	☐					
Pocket Doors	☐	☐					
Cabinet Hardware	☐	☐					
Ceiling Mirrors	☐	☐					
Shower Head	☐	☐					
Sink Head	☐	☐					
Upholstery-Front	☐	☐					
Upholstery-Rear	☐	☐					
Window Tint	☐	☐					
Windshield Rubber	☐	☐					

Fuel System

Fuel Level	☒	☐	1/2 TANK				
Level Low System	☒	☐	N/A.				

Bumpers

Front Bumper	☒	☐					
Rear Bumper	☐	☒	DAMAGED.				

Keys

Door Code/Keypad	☒	☒	N/A.				
Door	☐	☒	nono-				
Ignition	☒	☒	N/A				
Engine	☐	☒					
Bays	☐	☒					
Cabinets/Interior	☒	☒	N/A.				

Other

[illegible]

Electronics / Remotes

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Stereo Operational-F	☐	☐					
Stereo Operational-R	☐	☐					
TV - Front	☐	☐					
TV - Rear	☐	☐					
Generator Remote Start	☒	☒	N/A				
Genset Batteries	☒	☒	N/A				
Inverter Remote	☒	☒	N/A				
In-Motion Satellite Locks	☐	☐					
Speakers Operational	☐	☐					
Satellite Syst. Operational	☐	☐					

Ship to Shore Switch/Plug	☒	☒	N/A				
Interior Lights 12v	☒	☐					
Interior Lights 120v	☐	☐					
Light Switches	☐	☐					
Step Lights	☒	☐					
Buddy Light	☐	☐					
Driver Light	☒	☐					
Day/Night Shades	☐	☐					
Toilet	☐	☐					
Speedometer	☒	☐					
Fuel Gauge	☒	☐					
Temp Gauge	☒	☐					
Amp Gauge	☒	☐					
Volt Gauge	☒	☐					
DC Volt Gauge	☒	☐					

Operations

Roof Vent Fans	☐	☐					
Roof/Cruise Air Operational	☐	☐					
Roof/Cruise Air Filters	☐	☐					
Hot Water Heater	☐	☐					
Step Slide Operational	☒	☒	N/A				
Webasto	☐	☐					
Toe Kick Heaters	☐	☐					
Heat Pumps	☒	☒					
Fan Clutch	☒	☐					
City/Air Horn	☒	☐					
A/C Air Tank	☒	☐					
Alignment	☐	☐					

Bunk Lights	☒	☒	N/A				
Condo Curtains	☒	☒					
Bunk Curtains	☒	☒					
Mattresses	☒	☒					
Bunk TV's	☒	☒					

Busforsale.com ~ Bus Inspection

Bus Name: 0

Engine & Mechanical

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
ECM Codes	☐	☐					
House Alternator Charge	☐	☐					
Drive AC Operational	☐	☒					
Coach AC Operational	☐	☒	FRY SEAL IN COM. LEAKING				
Coach AC Components	☐	☒	LOW F REE				
HVAC Motor Brushes	☐	☒					
House Batteries	☒	☐	N/A				
Chassis Batteries	☐	☒	NEED REPAIRED				
Radiator Condition	☒	☐					
Belt Condition	☐	☒	NEED ALL NEW BELTS				
Charge Air Cooler	☒	☐					
Airbags	☐	☒	Steer and Tags				
Transmission Seal	☐	☒	outPut Seal leaking				
Rear Main Seal	☒	☐					
Pinion Seal	☐	☒	Bearing Case leaking on diff				
Mitre Box Seals	☐	☐	N/A				
50DN Seals	☐	☐	DUEL BOSCH				
Charging	☒	☐					
Mitre Box Dipstick	☒	☐	N/A				
Oil Dipstick	☒	☐					
Trans Dipstick	☒	☐					
Differential Oil	☒	☐					
Coolant Level	☒	☐					
Transmission Fluid Level	☒	☐					
Motor Oil Level	☒	☐					
Power Steering Level	☒	☐					
oil Pan	☐	☒	oil Pan Gasket leaking				

Body Damage	☐	☐	SEE LAST PAGE.				
Bay Door Shocks	☒	☐					
Bay Door Actuators	☒	☐					
Bay Door Operation	☒	☐					
Roof Inspection	☒	☐					
Roof Seals	☒	☐					
Mirror Chrome Condition	☐	☐	PAINTED				
Door Latches	☐	☐					
Trailer Wiring	☒	☐	N/A				
Rub Rails	☐	☐					
Side Glass	☐	☐					
Entrance Door Glass	☒	☐					
Shore Cord	☒	☐	N/A				
Awning Operable	☒	☐	N/A				
Docking Lights	☐	☐					
Mirror Operation	☐	☐					
Paint Repair	☐	☐	SEE LAST PAGE				

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
DATE	

MOTOR CARRIER OPERATOR	INSPECTOR'S NAME (PRINT OR TYPE)
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☐ YES
CITY, STATE, ZIP CODE	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				10. TIRES
			a. Service Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.				a. Tires on any steering axle of a power unit.
			b. Parking Brake System				b. Protection against shifting cargo.				b. All other tires.
			c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.				11. WHEELS AND RIMS
			d. Brake Hose								a. Lock or Side Ring
			e. Brake Tubing								b. Wheels and Rims
			f. Low Pressure Warning Device								c. Fasteners
			g. Tractor Protection Valve								d. Welds
			h. Air Compressor								12. WINDSHIELD GLAZING
			i. Electric Brakes								Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
			j. Hydraulic Brakes								13. WINDSHIELD WIPERS
			k. Vacuum Systems								Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			2. COUPLING DEVICES				7. STEERING MECHANISM				14. OTHER
			a. Fifth Wheels				a. Steering Wheel Free Play				List any other condition(s) which may prevent safe operation of this vehicle.
			b. Pintle Hooks				b. Steering Column				
			c. Drawbar/Towbar Eye				c. Front Axle Beam and All Steering Components Other Than Steering Column				
			d. Drawbar/Towbar Tongue				d. Steering Gear Box				
			e. Safety Devices				e. Pitman Arm				
			f. Saddle-Mounts				f. Power Steering				
			3. EXHAUST SYSTEM				g. Ball and Socket Joints				
			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.				h. Tie Rods and Drag Links				
			b. Bus exhaust system leaking or discharging in violation of standard.				i. Nuts				
			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.				j. Steering System				
			4. FUEL SYSTEM				8. SUSPENSION				
			a. Visible leak.				a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
			b. Fuel tank filler cap missing.				b. Spring Assembly				
			c. Fuel tank securely attached.				c. Torque, Radius or Tracking Components				
			5. LIGHTING DEVICES				9. FRAME				
			All lighting devices and reflectors required by Part 393 shall be operable.				a. Frame Members				
							b. Tire and Wheel Clearance				
							c. Adjustable Axle Assemblies (Sliding Subframes)				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION

✓ OK

X NEEDS REPAIR

NA



IF ITEMS DO NOT APPLY,

REPAIRED DATE


CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Bus Name:


0




Front View



Streetside View



Rear View



Curbside View