

Busforsale.com ~ Bus Inspection

Today's Date	<u>3/9/2026</u>	Bus Name	<u>MR4118</u>
Yr/Make/Model	<u>2015 MB Sprinter 3500</u>	VIN#	<u>WDAPF4CC4GP174118</u>
Mileage	<u>100,515</u>	Door Code	<u>N/A</u> Tech & Time:
Engine Type	<u>MB Turbo Diesel</u>	Transmission Type	<u>MB Automatic</u> Generator Gen Hours
Engine Serial #	Transmission Serial#		

DOT Compliance Items

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Driving Fog Lights *	☒	☐					
Gauge Lights *	☒	☐					
Dash Lights *	☒	☐					
ABS Light *	☒	☐					
Headlights *	☒	☐					
Brake Lights *	☒	☐					
Clearance Lights *	☒	☐					
Tail Lights *	☒	☐					
Turn Lights *	☒	☐					
Escape Hatch Operational *	☐ N/A	☐ N/A					
Windshield *	☒	☐					
Driver Glass *	☒	☐					
Windshield Wipers *	☒	☐					
Upper Control Arms *	☒	☐					
Lower Control Arms *	☒	☐					
Suspension - Front *	☒	☐					
Suspension - Rear *	☒	☐					
Power Steering *	☒	☐					
Exhaust System/Muffler *	☒	☐					

Brakes

Front % *	☒	☐	95%				
Drive % *	☒	☐	50%				
Tag% *	☐ N/A	☐ N/A					
Retarder *	☐ N/A	☐ N/A					
Shock - Front *	☒	☐					
Shock - Rear *	☒	☐					

Tires

Front % *	☒	☐	13/32 14.32 - DOT 2024				
Drive % *	☒	☐	14/32 14/32 14/32 14/32 - DOT 2024				
Tag % *	☐ N/A	☐ N/A					
Wheelseals - Front *	☒	☐					
Wheelseals - Rear *	☒	☐					

Seat Belts

Driver *	☒	☐					
Jump *	☒	☐					
Passenger (if applicable) *	☐	☐					

Other

Brake Light	☐	☒	brake light illuminated on dash				
SRS light	☐	☒	on (need dealer repair)				
Restraint Light	☐	☒	on (need dealer repair)				
	☐	☐					
	☐	☐					

Conversion / Bus Interior							
	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Smoke/Co2 Detector	N/A	N/A					
Switch Lights	X						
Switch Identification	X						
Water Pump Operation	X						
Fresh Water Drain	X						
Sewer Drain	X						
Air Vents Dash	X						
Air Vents Coach	X						
Driver Stereo		X	would not power up				
BackUp Camera		X	would not power up				
Driver Seat Operation	X						
Driver Seat	X						

Finishes						
Tile Condition	X					
Laminate Condition	X					
Shower Operational			did not test - no water			
Air Pocket Doors	N/A	N/A				
Pocket Doors	N/A	N/A				
Cabinet Hardware	X					
Ceiling Mirrors	N/A	N/A				
Shower Head			did not test - no water			
Sink Head			did not test - no water			
Upholstery-Front	X					
Upholstery-Rear	X					
Window Tint	X					
Windshield Rubber	X					

Fuel System							
Fuel Level							
Level Low System	N/A	N/A					

			Bumpers				
Front Bumper	☐	☒	paint peeling off				
Rear Bumper	☐	☐					

Keys						
Door Code/Keypad	N/A	N/A				
Door	X					
Ignition	X					
Engine	N/A	N/A				
Bays	X					
Cabinets/Interior	N/A	N/A				

Other							

Electronics / Remotes

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Stereo Operational-F	☒	☐					
Stereo Operational-R	☒	☐					
TV - Front	☒	☐					
TV - Rear	☐	☐					
Generator Remote Start	☒	☐					
Genset Batteries	☒	☐					
Inverter Remote	☐	☐	inoperable				
In-Motion Satellite Locks	☐	☐					
Speakers Operational	☐	☐					
Satellite Syst. Operational	☐	☐					
	☐	☐					

Switches / Gauges / Lights

Ship to Shore Switch/Plug	☒	☐					
Interior Lights 12v	☒	☐					
Interior Lights 120v	☒	☐					
Light Switches	☒	☐					
Step Lights	☐	☐					
Buddy Light	☒	☐					
Driver Light	☒	☐					
Day/Night Shades	☒	☐					
Toilet	☐	☐	did not test - no water				
Speedometer	☒	☐					
Fuel Gauge	☒	☐					
Temp Gauge	☒	☐					
Amp Gauge	☐	☐					
Volt Gauge	☒	☐					
DC Volt Gauge	☐	☐					

Operations

Roof Vent Fans	☒	☐					
Roof/CruiseAir Operational	☒	☐					
Roof/Cruise Air Filters	☒	☐					
Hot Water Heater	☐	☐	did not test - no water				
Step Slide Operational	☐	☐					
Webasto	☐	☐					
Toe Kick Heaters	☐	☐					
Heat Pumps	☒	☐					
Fan Clutch	☒	☐					
City/Air Horn	☒	☐					
A/C Air Tank	☒	☐					
Alignment	☒	☐					

Bunks

Bunk Lights	☐	☐					
Condo Curtains	☐	☐					
Bunk Curtains	☐	☐					
Mattresses	☒	☐					
Bunk TV's	☐	☐					
	☐	☐					

Engine & Mechanical							
	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
ECM Codes			could not test				
House Alternator Charge	N/A	N/A					
Drive AC Operational	X						
Coach AC Operational	X						
Coach AC Components	X						
HVAC Motor Brushes	X						
House Batteries	X						
Chassis Batteries	X						
Radiator Condition	X						
Belt Condition	X						
Charge Air Cooler	N/A	N/A					
Airbags	N/A	N/A					
Transmission Seal	X						
Rear Main Seal	X						
Pinion Seal	X						
Mitre Box Seals	N/A	N/A					
50DN Seals	N/A	N/A					
Charging	X						
Mitre Box Dipstick	N/A	N/A					
Oil Dipstick	X						
Trans Dipstick	N/A	N/A					
Differential Oil	X						
Coolant Level	X						
Transmission Fluid Level	X						
Motor Oil Level	X						
Power Steering Level	X						
Exterior							
Body Damage		X	see page six (6)				
Bay Door Shocks	N/A	N/A					
Bay Door Actuators	N/A	N/A					
Bay Door Operation	X						
Roof Inspection	X						
Roof Seals	X						
Mirror Chrome Condition			painted				
Door Latches	X						
Trailer Wiring	X						
Rub Rails	X						
Side Glass	X						
Entrance Door Glass	X						
Shore Cord		X	no cord				
Awning Operable			did not test				
Docking Lights	N/A	N/A					
Mirror Operation	X						
Paint Repair		X	see page six (6)				

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
DATE	

MOTOR CARRIER OPERATOR	INSPECTOR'S NAME (PRINT OR TYPE)
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☐ YES
CITY, STATE, ZIP CODE	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒			1. BRAKE SYSTEM				6. SAFE LOADING	☒			10. TIRES
☒			a. Service Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	☒			a. Tires on any steering axle of a power unit.
☒			b. Parking Brake System	☒			b. Protection against shifting cargo.	☒			b. All other tires.
☒			c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.	☒			11. WHEELS AND RIMS
☒			d. Brake Hose					☒			a. Lock or Side Ring
☒			e. Brake Tubing					☒			b. Wheels and Rims
☒			f. Low Pressure Warning Device	N/A				☒			c. Fasteners
☒			g. Tractor Protection Valve					☒			d. Welds
☒			h. Air Compressor	N/A							12. WINDSHIELD GLAZING
☒			i. Electric Brakes								Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
☒			j. Hydraulic Brakes					☒			13. WINDSHIELD WIPERS
☒			k. Vacuum Systems	☒				☒			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			2. COUPLING DEVICES	☒			7. STEERING MECHANISM				14. OTHER
			a. Fifth Wheels				a. Steering Wheel Free Play				List any other condition(s) which may prevent safe operation of this vehicle.
			b. Pintle Hooks	☒			b. Steering Column				
			c. Drawbar/Towbar Eye				c. Front Axle Beam and All Steering Components Other Than Steering Column				
			d. Drawbar/Towbar Tongue	☒			d. Steering Gear Box	☒			
			e. Safety Devices	☒			e. Pitman Arm				
			f. Saddle-Mounts	☒			f. Power Steering				
			3. EXHAUST SYSTEM	☒			g. Ball and Socket Joints				
			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	☒			h. Tie Rods and Drag Links				
			b. Bus exhaust system leaking or discharging in violation of standard.	☒			i. Nuts				
			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	☒			j. Steering System				
			4. FUEL SYSTEM				8. SUSPENSION				
			a. Visible leak.	☒			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
			b. Fuel tank filler cap missing.				b. Spring Assembly				
			c. Fuel tank securely attached.	☒			c. Torque, Radius or Tracking Components				
			5. LIGHTING DEVICES	☒			9. FRAME				
			All lighting devices and reflectors required by Part 393 shall be operable.	N/A			a. Frame Members				
							b. Tire and Wheel Clearance				
							c. Adjustable Axle Assemblies (Sliding Subframes)				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, ☒ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Bus Name:

MR4118

