

Today's Date **8/18/2026** Bus Name **Gator**
 Yr/Make/Model **2002³ Prevost XLII** VIN# **2PCY43349731028021**
 Mileage **speed- 440834/ECM - 697539** Door Code **17535** Tech & Time: **2.5**
 Engine Type **Detroit 60 Series** Transmission Type **Allison B500** Generator **Gen Hours**
 Engine Serial # **06R0698319** Transmission Serial# **139791** **1,780**

DOT Compliance Items

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Driving Fog Lights *	☐	☒	1	1	\$27.00		0.25
Gauge Lights *	☒	☐					
Dash Lights *	☒	☐					
ABS Light *	☐	☒	ON				TBD
Headlights *	☒	☐					
Brake Lights *	☒	☐					
Clearance Lights *	☐	☒	1 UPPER AMBER OUT	1	\$30.00		0.5
Tail Lights *	☒	☐					
Turn Lights *	☒	☐					
Escape Hatch Operational *	☒	☐					
Windshield *	☒	☐					
Driver Glass *	☒	☐					
Windshield Wipers *	☒	☐					
Upper Control Arms *	☐	☒	NEEDS REPLACED	2	\$645.00		8
Lower Control Arms *	☒	☐	NEW AND NEW TIE RODS				
Suspension - Front *	☒	☐					
Suspension - Rear *	☒	☐					
Power Steering *	☒	☐					
Exhaust System/Muffler *	☐	☐					

Brakes

Front % *	☒	☐	60% REMAINING				
Drive % *	☒	☐	60% REMAINING				
Tag % *	☒	☐	60% REMAINING				
Jake Brake *	☒	☐					
Shock - Front *	☒	☐					
Shock - Rear *	☒	☐					

Tires

Front % *	☐	☒	14/32 L-STEER- 3/32 DOT 2022 DOT 2023		\$12.00		1.5
Drive % *	☐	☒	15/32 6/32 5/32 5/32 DOT 2022	2	\$1,100.00		2.5
Tag % *	☒	☐					
Wheelseals - Front *	☒	☐					
Wheelseals - Rear *	☒	☐					

Seat Belts

Driver *	☒	☐					
Jump *	☐	☒	NONE	1	\$69.00		1
Passenger (if applicable) *	☐	☐	N/A				

Other

DS-DRIVE CALIPER	☐	☒	NEEDS REPLACED (P/N R/T)		\$147.00		2
FRAME ROT	☐	☒	EXCESSIVE AT FUEL TAML & AT FRT AXLE		\$10,000.00		
	☐	☐	ALSO UNDER RADIATOR				
	☐	☐					
	☐	☐					

Bus Name: **Gator****Conversion / Bus Interior**

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Smoke/Co2 Detector	☒	☐					
Switch Lights	☒	☐					
Switch Identification	☒	☐					
Water Pump Operation	☐	☐	NO WATER - DID NOT TEST				
Fresh Water Drain	☒	☐					
Sewer Drain	☒	☐					
Air Vents Dash	☒	☐					
Air Vents Coach	☐	☒	NEEDS 3	3		\$49.00	0.75
Driver Stereo	☐	☒	NO FACE PLATE - RADIO INOPERABLE				TBD
BackUp Camera	☐	☐	N/A				TBD
Driver Seat Operation	☒	☐					
Driver Seat	☒	☐					
	☐	☐					

Finishes

Tile Condition	☒	☐					
Laminate Condition	☒	☐					
Shower Operational	☒	☐	N/A				
Air Pocket Doors	☒	☐	N/A				
Pocket Doors	☒	☐					
Cabinet Hardware	☒	☐					
Ceiling Mirrors	☒	☐					
Shower Head	☐	☐	N/A				
Sink Head	☒	☐					
Upholstery-Front	☒	☐					
Upholstery-Rear	☒	☐					
Window Tint	☒	☐					
Windshield Rubber	☒	☐					

Fuel System

Fuel Level	☒	☐	1/4 TANK				
Level Low System	☒	☐					

Bumpers

Front Bumper	☒	☐					
Rear Bumper	☐	☒	BENT - FIBERGLASS BROKEN				TBD

Keys

Door Code/Keypad	☒	☐	17535 - WORKING				
Door	☒	☐					
Ignition	☒	☐					
Engine	☒	☐					
Bays	☒	☐					
Cabinets/Interior	☒	☐	N/A				

Other

TRANS DIPSTICK	☐	☒	TUBE GROMMET LEAKING	1		\$21.00	1.5
GEN SET	☐	☒	REAR MAIN LEAKING	1		\$160.00	5.5
	☐	☐					
	☐	☐					
	☐	☐					

Bus Name: **Gator****Electronics / Remotes**

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
Stereo Operational-F	☐	☒	NO SOUND				TBD
Stereo Operational-R	☒	☐					
TV - Front	☒	☐					
TV - Rear	☒	☐					
Generator Remote Start	☐	☒	NONE - STARTS AND RUNS FROM BELOW				TBD
Genset Batteries	☒	☐					
Inverter Remote	☒	☐					
In-Motion Satellite Locks	☐	☐	UNKNOWN				
Speakers Operational	☒	☐					
Satellite Syst. Operational	☐	☐	UNKNOWN				
	☐	☐					

Switches / Gauges / Lights

Ship to Shore Switch/Plug	☒	☐					
Interior Lights 12v	☒	☐					
Interior Lights 120v	☒	☐					
Light Switches	☒	☐					
Step Lights	☒	☐					
Buddy Light	☒	☐					
Driver Light	☒	☐					
Day/Night Shades	☒	☐					
Toilet	☒	☐					
Speedometer	☒	☐					
Fuel Gauge	☒	☐					
Temp Gauge	☒	☐					
Amp Gauge	☒	☐					
Volt Gauge	☒	☐					
DC Volt Gauge	☒	☐					

Operations

Roof Vent Fans	☐	☐	N/A				
Roof/Cruise Air Operational	☐	☐					
Roof/Cruise Air Filters	☐	☐					
Hot Water Heater	☐	☐	N/A				
Step Slide Operational	☐	☐	N/A				
Webasto	☐	☐	N/A				
Toe Kick Heaters	☐	☐	N/A				
Heat Pumps	☐	☐					
Fan Clutch	☐	☒	LOCKED IN	1		\$2,100.00	3
City/Air Horn	☒	☐					
A/C Air Tank	☒	☐					
Alignment	☐	☒	NEEDS ALIGNMENT AND NEW STEER TIRES				TBD

Bunks

Bunk Lights	☒	☐					
Condo Curtains	☐	☐	NONE				
Bunk Curtains	☒	☐					
Mattresses	☒	☐					
Bunk TVs	☐	☐	N/A				
	☐	☐					

Bus Name: **Gator****Engine & Mechanical**

	OK	Repair	Technician's Notes:	Qty:	Per Piece:	Price:	Labor:
ECM Codes	☒	☐	NONE				
House Alternator Charge	☒	☐					
Drive AC Operational	☐	☐	NO BELTS- COULD NOT TEST			\$78.00	TBD
Coach AC Operational	☐	☐					
Coach AC Components	☐	☒	NO BELTS - COULD NOT TEST				
HVAC Motor Brushes	☒	☐					
House Batteries	☐	☒	NEEDS REPLACED	2	4D AGM	\$340.00	1
Chassis Batteries	☒	☐					
Radiator Condition	☒	☐					
Belt Condition	☒	☐					
Charge Air Cooler	☒	☐					
Airbags	☐	☒	NEEDS BOTH REAR DRIVE AXLE BAGS	2		\$200.99	2.5
Transmission Seal	☒	☐					
Rear Main Seal	☒	☐					
Pinion Seal	☒	☐					
Mitre Box Seals	☒	☐					
50DN Seals	☐	☐	DUEL BOSCH				
Charging	☒	☐					
Mitre Box Dipstick	☒	☐					
Oil Dipstick	☒	☐					
Trans Dipstick	☒	☐					
Differential Oil	☒	☐					
Coolant Level	☒	☐					
Transmission Fluid Level	☒	☐					
Motor Oil Level	☒	☐					
Power Steering Level	☒	☐					
	☐	☐					
	☐	☐					

Exterior

Body Damage	☐	☐	SEE LAST PAGE				
Bay Door Shocks	☐	☒	NEEDS 2	2		\$14.00	0.25
Bay Door Actuators	☒	☐					
Bay Door Operation	☒	☐					
Roof Inspection	☒	☐					
Roof Seals	☒	☐					
Mirror Chrome Condition	☒	☐					
Door Latches	☒	☐					
Trailer Wiring	☒	☐					
Rub Rails	☒	☐					
Side Glass	☒	☐					
Entrance Door Glass	☒	☐					
Shore Cord	☒	☐					
Awning Operable	☐	☐	N/A				
Docking Lights	☒	☐					
Mirror Operation	☒	☐					
Paint Repair	☒	☐					
	☐	☐					

Gator

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER FLEET UNIT NUMBER

DATE

MOTOR CARRIER OPERATOR

INSPECTOR'S NAME (PRINT OR TYPE)

ADDRESS

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☐ YES

CITY, STATE, ZIP CODE

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHERVEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS
☐ (OTHER)

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			1. BRAKE SYSTEM	✓			6. SAFE LOADING				10. TIRES
✓			a. Service Brakes				a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.				a. Tires on any steering axle of a power unit.
✓			b. Parking Brake System				b. Protection against shifting cargo.				b. All other tires.
✓			c. Brake Drums or Rotors				c. Container securement devices on intermodal equipment.				11. WHEELS AND RIMS
✓			d. Brake Hose								a. Lock or Side Ring
✓			e. Brake Tubing								b. Wheels and Rims
✓			f. Low Pressure Warning Device								c. Fasteners
✓			g. Tractor Protection Valve								d. Welds
✓			h. Air Compressor								12. WINDSHIELD GLAZING
✓			i. Electric Brakes								Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).
✓			j. Hydraulic Brakes								13. WINDSHIELD WIPERS
✓			k. Vacuum Systems								Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
N/A			2. COUPLING DEVICES				7. STEERING MECHANISM				14. OTHER
✓			a. Fifth Wheels				a. Steering Wheel Free Play				List any other condition(s) which may prevent safe
✓			b. Pintle Hooks				b. Steering Column				FOG LIGHT
✓			c. Drawbar/Towbar Eye				c. Front Axle Beam and All Steering Components Other Than Steering Column				MARKER LIGHTS
✓			d. Drawbar/Towbar Tongue				d. Steering Gear Box				FRAME ROT
✓			e. Safety Devices				e. Pitman Arm				UPPER CONTROL ARMS
✓			f. Saddle-Mounts				f. Power Steering				DRIVE AXLE CALIPER
✓			3. EXHAUST SYSTEM				g. Ball and Socket Joints				AIR BAGS
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.				h. Tie Rods and Drag Links				TIRES
✓			b. Bus exhaust system leaking or discharging in violation of standard.				i. Nuts				
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.				j. Steering System				
✓			4. FUEL SYSTEM				8. SUSPENSION				
✓			a. Visible leak.				a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.				
✓			b. Fuel tank filler cap missing.				b. Spring Assembly				
✓			c. Fuel tank securely attached.				c. Torque, Radius or Tracking Components				
✓			5. LIGHTING DEVICES				9. FRAME				
✓			All lighting devices and reflectors required by Part 393 shall be operable.				a. Frame Members				
✓							b. Tire and Wheel Clearance				
✓							c. Adjustable Axle Assemblies (Sliding Subframes)				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION. ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

© Copyright 2010 J. J. KELLER & ASSOCIATES, INC.®
Neenah, WI • USA • (800) 327-6808
jjkeller.com • Printed in the United States

ORIGINAL

400-FS-C2 3127
Rev. 6/10

Bus Name: **Gator**

